

286-191

D.L.S. HENDERSON

162.50'

326.00'E

edge

road north in

P.T.C. Lines  
10. ST. PT. NO. 603  
40' DEEP ROAD

Slope 1 in

Slope 2 in

over dimensions  
and slopes work correctly  
but at corners it seems to  
be necessary to remove some of the  
material.